



# MSTFLINT Package - Firmware Burning and Diagnostics Tools Release Notes

---

Rev 4.7.0



NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT ("PRODUCT(S)") AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES "AS IS" WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS THE CUSTOMERS MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT ARE DISCLAIMED IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies  
350 Oakmead Parkway Suite 100  
Sunnyvale, CA 94085  
U.S.A.  
www.mellanox.com  
Tel: (408) 970-3400  
Fax: (408) 970-3403

© Copyright 2017. Mellanox Technologies Ltd. All Rights Reserved.

Mellanox®, Mellanox logo, Accelio®, BridgeX®, CloudX logo, CompustorX®, Connect-IB®, ConnectX®, CoolBox®, CORE-Direct®, EZchip®, EZchip logo, EZappliance®, EZdesign®, EZdriver®, EZsystem®, GPUDirect®, InfiniHost®, InfiniBridge®, InfiniScale®, Kotura®, Kotura logo, Mellanox CloudRack®, Mellanox CloudXMellanox®, Mellanox Federal Systems®, Mellanox HostDirect®, Mellanox Multi-Host®, Mellanox Open Ethernet®, Mellanox OpenCloud®, Mellanox OpenCloud Logo®, Mellanox PeerDirect®, Mellanox ScalableHPC®, Mellanox StorageX®, Mellanox TuneX®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, NP-1c®, NP-2®, NP-3®, Open Ethernet logo, PhyX®, PlatformX®, PSIPHY®, SiPhy®, StoreX®, SwitchX®, Tiler®, Tiler logo, TestX®, TuneX®, The Generation of Open Ethernet logo, UFM®, Unbreakable Link®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

For the most updated list of Mellanox trademarks, visit <http://www.mellanox.com/page/trademarks>

## Table of Contents

<b>Table of Contents</b> .....	<b>3</b>
<b>List of Tables</b> .....	<b>4</b>
<b>Chapter 1 Overview</b> .....	<b>6</b>
1.1 Package Tools .....	6
1.2 Supported Operating Systems and Platforms .....	7
1.3 Supported Flash Types .....	9
1.4 Supported Mellanox ICs .....	9
<b>Chapter 2 Changes and New Features in Rev 4.7.0.</b> .....	<b>10</b>
<b>Chapter 3 Known Issues</b> .....	<b>11</b>
<b>Chapter 4 Bug Fixes History</b> .....	<b>13</b>
<b>Chapter 5 History of Changes and New Features</b> .....	<b>14</b>



## List of Tables

Table 1:	Release Update History	5
Table 2:	mstflint Available Tools	6
Table 3:	Supported Operating Systems and Platforms	7
Table 4:	Supported Flash Types	9
Table 5:	Mellanox IC Devices	9
Table 6:	Changes and New Features in Rev 4.7.0	10
Table 7:	Known Issues and Limitations	11
Table 8:	Bug Fixes History	13
Table 9:	History of Changes and New Features	14

## Release Update History

*Table 1 - Release Update History*

Release	Date	Description
Rev 4.7.0	June 28, 2017	Initial release of this mstflint version

# 1 Overview

These are the release notes for Rev 4.7.0 of the mstflint.

This release supports the following operating systems: Linux. Please see the supported platform table for further details.

The tools functionality is identical in all operating systems unless otherwise noted.

## 1.1 Package Tools

The following is a list of the available tools in the package, together with a brief description of each tool. The tools apply to single switch systems or adapter cards. The mstflint tools do not provide cluster wide functionality.

**Table 2 - mstflint Available Tools**

Category	Tool	Description
Firmware Update and Configuration	mstflint	This tool burns a firmware binary image or an expansion ROM image to the Flash of a Mellanox network adapter/switch device. It includes query functions to the burnt firmware image and to the binary image file.
	mstconfig	Allows the user to change some of the device configurations without having to create and burn a new firmware.
Debug and Diagnostics Utilities	mstregdump	Dumps device internal configuration data.
	mstmcr	Reads/writes a single word from/to a device configuration register space

Detailed installation instructions along with complete descriptions of the various tools in the package can be found in the *Mellanox Firmware Tools User's Manual*.

## 1.2 Supported Operating Systems and Platforms

mstflint is supported on the following platforms:.

**Table 3 - Supported Operating Systems and Platforms**

OS	Arch
RHEL6.2	64 Bit
RHEL6.3	64Bit
RHEL 6.4	64 Bit
RHEL6.5	64 Bit
RHEL6.6	64 Bit
RHEL6.7	64 Bit
RHEL6.7	PPC64
RHEL6.8	64 Bit
RHEL6.9	64 Bit
RHEL6.9	PPC64
RHEL7.0	64 Bit
RHEL7.1	64 Bit
RHEL7.2	64 Bit
RHEL7.2	PPC64
RHEL7.2	PPC64LE [Power8]
RHEL7.2	ARM
RHEL7.3	64 Bit
RHEL7.3	PPC64
RHEL7.3	PPC64LE [Power8]
RHEL7.3	ARM
Debian 8.0	64 Bit
Debian 8.1	64 Bit
Debian 8.2	64 Bit
Debian 8.3	64 Bit
Debian 8.7 [Kernel 4.4]	64 Bit
Debian 7.11	64 Bit
Fedora 20	64 Bit
Fedora 21	64 Bit
Fedora 23	64 Bit
Fedora 23	PPC64LE [Power 8]
Fedora 24	64 Bit
OEL 6.6	64 Bit

**Table 3 - Supported Operating Systems and Platforms**

OS	Arch
OEL 6.7	64 Bit [UEK]
OEL 6.8	64 Bit
OEL 7.1	64 Bit [UEK 3]
OEL 7.2	64 Bit [UEK 3]
Sles11 SP3	64 Bit
Sles11 SP4	64 Bit
Sles11 SP4	PPC64
Sles12	64 Bit
Sles12SP1	64 Bit
Sles12SP1	PPC64LE
Sles12SP2	64 Bit
Sles12SP2	PPC64LE
XenServer6.5	64 Bit
XenServer7.0	64 Bit
WindRiver6.0	64 Bit
Ubuntu 12.04.5	64 Bit
Ubuntu 14.04	64 Bit
Ubuntu 14.04	PPC64LE [Power 8]
Ubuntu 14.10	64 Bit
Ubuntu 15.04	64 Bit
Ubuntu 15.10	64 Bit
Ubuntu 16.04	64 Bit
Ubuntu 16.10	64 Bit
Ubuntu 17.04	64 Bit
Kernel.org 4.7	x86_64
Kernel.org 4.8	x86_64
Kernel.org 4.9	x86_64
Kernel.org 4.10	x86_64
Kernel.org 4.11	x86_64



### 1.3 Supported Flash Types

mstflint supports the following Flash types.

**Table 4 - Supported Flash Types**

Vendor	Flash Family	Tested P/N
Micron	M25Pxx	M25P16
	M25PXxx	M25PX16
	N25Qxxx	N25Q032
Winbond	W25QxxBV	W25Q32BV
Spansion	S25FL11xx	S25FL116K
Atmel	AT25DFxxx	AT25DF161

### 1.4 Supported Mellanox ICs

With respect to mstflint, Mellanox IC devices are divided into two groups: Group I and Group II (4th generation and 5th generation, respectively). The ICs are listed in the following table:

**Table 5 - Mellanox IC Devices**

IC Group	IC Device
Group I/4th Generation	<ul style="list-style-type: none"> <li>• ConnectX@-3</li> <li>• ConnectX@-3 Pro</li> <li>• SwitchX@</li> <li>• SwitchX@-2</li> </ul>
Group II/5th Generation	<ul style="list-style-type: none"> <li>• Connect-IB@</li> <li>• Switch-IB™</li> <li>• Switch-IB™ 2</li> <li>• Spectrum™</li> <li>• ConnectX@-4</li> <li>• ConnectX@-4 Lx</li> <li>• ConnectX@-5</li> <li>• ConnectX@-5 Ex</li> </ul>

## 2 Changes and New Features in Rev 4.7.0

*Table 6 - Changes and New Features in Rev 4.7.0*

Component/ Tool	Description	Operating System
Secure Firmware Update	Added support for Secure Firmware Update in ConnectX-4 and ConnectX-4 Lx.	Linux
Build	Added a new flag to configure '--enable-openssl' which will enable all the openssl features in the tools, like the CheckSum, and sign images	Linux
mstflint	Added sign command for secured images. This feature is available only if the package was configured and compiled with '--enable-openssl'.	Linux
	Added a flag to enforce working in a non-secure mode, if available (according to security type).	
	Added expansion ROM CPU architecture to the flint query when the expansion ROM is available.	All
mstconfig	Added new mstconfig TLVs.	All
	Added support for generating and applying TLV configuration files.	All

For further information, please refer to the MFT User Manual.

### 3 Known Issues

The following table provides a list of known issues and limitations in regards to this release of the Mellanox Firmware Tools.

**Table 7 - Known Issues and Limitations (Sheet 1 of 2)**

Internal Ref.	Issue
207320/ 933032	<b>Description:</b> Tools that run in parallel on the same device may interrupt one another, and may cause the device to be in an undefined state.
	<b>Workaround:</b> Avoid running more than a single tool at a time with the same device
	<b>Keywords:</b> General
592673	<b>Description:</b> PCI access in PowerPC machines is up to 10 times slower than other platforms, therefore, there are performance issues on all tools running on PowerPC machines.
	<b>Workaround:</b> N/A
	<b>Keywords:</b> General
607508	<b>Description:</b> Wrong localization settings in the operating system cause some tools to fail with error: locale::facet::_S_create_c_locale name not valid
	<b>Workaround:</b> Run: <code>export LC_ALL=C</code>
	<b>Keywords:</b> General
676412	<b>Description:</b> Aggressive killing of a tool that is locking the vendor specific semaphore (in ConnectX-4/ConnectX-4 Lx devices) will leave the semaphore locked, and any tool will get stuck waiting for semaphore.
	<b>Workaround:</b> Run: <code>mstmcrs -c &lt;pci device&gt;</code>
	<b>Keywords:</b> General
-	<b>Description:</b> Firmware burn will fail due to invalid/old timestamp on ConnectX-4/ConnectX-4 Lx devices running these firmware versions: 12.14.0060/14.14.0060, or 12.14.0074/14.14.0075
	<b>Workaround:</b> Use mstflint v4.1.0 to upgrade/downgrade the firmware version.
	<b>Keywords:</b> Firmware Burning Tools
692397	<b>Description:</b> On ConnectX-3/ConnectX-3 Pro adapter cards, when burning a new firmware image that does not contain an expansion ROM on a flash that contains firmware and expansion ROM, the burning tool will save the expansion ROM in the flash.
	<b>Workaround:</b> This issue can be avoided by: 1. Removing the ROM from the flash before the FW update process by running the following mstflint command: <code>mstflint -d &lt;dev&gt; --allow_rom_change drom</code> 2. Adding the <code>--use_image_rom</code> flag to the mstflint FW update command
	<b>Keywords:</b> Firmware Burning Tools

**Table 7 - Known Issues and Limitations (Sheet 2 of 2)**

Internal Ref.	Issue
534010/ 647911	<b>Description:</b> mstconfig allows setting port parameters for both ports from a single function on ConnectX-4. This poses a security issue since a certain physical function is able to change port parameters for all ports regardless of its designated port.
	<b>Workaround:</b> N/A
	<b>Keywords:</b> mstconfig
221201	<b>Description:</b> The firmware update process in Connect-IB™, Switch-IB™, ConnectX®-4, ConnectX®-4 Lx and ConnectX®-5 and may take up to two minutes.
	<b>Workaround:</b> N/A
	<b>Keywords:</b> mstflint
326763	<b>Description:</b> The sg command on Connect-IB™, Switch-IB™, ConnectX®-4, ConnectX®-4 Lx and ConnectX®-5 fails if the <code>-override_cache_replacement</code> flag is not used.
	<b>Workaround:</b> Set the GUIDs only when firmware is not active (driver is not loaded) by using the flag <code>-override_cach_replacement</code>
	<b>Keywords:</b> mstflint
409212/ 408374	<b>Description:</b> Attempting to access Remote/MTUSB device for parallel does not work well.
	<b>Workaround:</b> Avoid working in parallel through these interfaces.
	<b>Keywords:</b> mstflint
540073	<b>Description:</b> Attempt to burn firmware while specifying the <code>-use_fw</code> flag fails as firmware does not support write operation on this flash.
	<b>Workaround:</b> Do not use the <code>-use_fw</code> flag for burn operations.
	<b>Keywords:</b> mstflint
927526	<b>Description:</b> When running the mstconfig query after mstconfig reset, the mstconfig query does not show the correct configuration that should be loaded upon the next boot.
	<b>Workaround:</b> To view the default configuration (under the Default column) run: <code>mstconfig -d &lt;device&gt; -e query.</code>
	<b>Keywords:</b> mstconfig
1063778	<b>Description:</b> Secure firmware Update: The flint brom and drom commands are not supported.
	<b>Workaround:</b> N/A
	<b>Keywords:</b> Secure Firmware Update,, flint

## 4 Bug Fixes History

Table 8 lists the history of bugs fixed

**Table 8 - Bug Fixes History**

Internal Ref.	Issue
691073	<b>Description:</b> In Linux, updating firmware on an unmanaged InfiniScale IV switch by Inband fails with the following error: MFE_SEM_LOCKED
	<b>Keywords:</b> Firmware Burning Tools
	<b>Discovered in Release:</b> 4.3.0
	<b>Fixed in Release:</b> 4.4.0
702505/ 735109	<b>Description:</b> Fixed an issue which caused mstflint brom/drom operations to fail when using 5th Generation devices firmware.
	<b>Keywords:</b> mstflint
	<b>Discovered in Release:</b> 4.3.0
	<b>Fixed in Release:</b> 4.4.0

## 5 History of Changes and New Features

**Table 9 - History of Changes and New Features**

Component / Tool	Description	Operating System
<b>Rev. 4.6.0</b>		
Adapter Cards	Added support for ConnectX-5/ConnectX-5 Ex adapter cards.  <b>Note:</b> ConnectX-5/ConnectX-5 Ex adapter cards are currently at <b>Beta</b> level.	All
mstconfig	Added an option to query active (current) configurations in mlx-config.	All
	Added new parameters in VPI settings configuration: XFI_MODE, PHY_TYPE, FORCE_MODE	
	Added a new parameter to the PCI configuration NON_PREFETCHABLE_PF_BAR	
<b>Rev. 4.5.0</b>		
General	Added support for Innova IPsec 4 Lx EN /Innova Flex 4 Lx EN	Linux
mstconfig	Enabled mlxconfig to work with a database that describes the meta data of the TLVs configuration of fifth generation devices.	All
	Added the following configuration TLVs to mlxconfig: <ul style="list-style-type: none"> <li>• MPFS</li> <li>• KEEP LINK UP</li> <li>• SW OFFLOAD CONF</li> </ul>	All
mstflint	Added support for viewing and changing OEMs' device flash parameters using an IB device when using flint.	All
<b>Rev. 4.4.0</b>		
mstconfig	Added the following new configurations: <ul style="list-style-type: none"> <li>• Number of TCs</li> <li>• Number of VLs</li> <li>• Enable DCBX in CEE mode</li> <li>• Enable DCBX in IEEE mode</li> <li>• Allow the NIC to accept DCBX configuration from the remote peer</li> <li>• Enable DCBX</li> <li>• Enable the internal LLDP client</li> <li>• Select which LLDP TLV will be generated by the NIC</li> </ul>	All
General	Added support for all tools to work when the MST driver is not installed	Linux
mstregmcra	Added support for clearing VSEC PCI semaphore by the mstregmcra tool. The new capability can be used after killing a tool forcefully without clearing the semaphores. Supported devices: ConnectX-4, ConnectX-4 Lx and Connect-IB	All

Component / Tool	Description	Operating System
mstconfig	Added a backup command in mstconfig which allows user to save backup of the non-volatile configurations in a RAW file. This file can be set on the device by using the <code>set_raw</code> command	All
<b>Rev. 4.3.0</b>		
General	Added support for Spectrum device.	All
	Added support for Switch-IB 2 device.	All
	4th generation and 5th generation IC devices are now also named Group I ICs and Group II ICs, respectively.	N/A
mstconfig	Added support for setting some of the parameters in textual values in addition to numerical values.	All
	Added new configurations: <ul style="list-style-type: none"> <li>• The PF log bar size</li> <li>• The VF log bar size</li> <li>• The number of PF MSIX</li> <li>• The number of VF MSIX</li> <li>• port owner</li> <li>• Allow RD counters</li> <li>• IP protocol used by flexboot</li> </ul>	All
	Added the option to display the configuration's default values.	All
mstflint	Added support to calculate checksum on selected sections in the firmware image.	All
	Added the option to attach a timestamp to the firmware image.	All
Burning Tools	Improved firmware burn performance in livefish mode on 5th generation devices.	All
	Added the ability to show the running firmware version in case it does not match with the burnt firmware version on the flash. This case generally occurs after firmware upgrade and before firmware reload.	All