

Initially, the machine was working properly and burned so (30*40 mm)



After upgrading, it turns out:



Even if the code does not change, the shift occurs in different places.

The offset occurs in any mode when filling diagonally and horizontally:



I drew a line offset (20*30 mm)

Sometimes even this shift several times in one picture



Here you can see that the internal filling were shifted and after that the border is performed correctly:

(50*70 mm)

